

Eccentric Slotter

The next process after cutting and creasing of the sheet is slotting and corner cutting. It is simultaneously carried over this machine. Three slotting and one corner cutting die can be easily adjusted by gear rack mechanism. The upper dies move in an arc so that the board is slotted in a shearing manner. Two guides are provided on the feed table to support the sheets while cutting.



Size	Motor H.P.	Max.Slot	Weight Aprx.[MT]	Floor Space
65"	2	17"	1.8	7'x4'
75"	3	18"	2.2	8'x4'
85"	3	18"	2.4	9'x4'
95"	5	18"	3'	10'x4'