

Pneumatic Pump

The pumps work with a pneumatic pressure of Max.4 kgs psi, and require no electric power. Hence, the savings are quite high. As well as it's Not Require any Motor (The special features are Heavy viscosity color easily lifted with this pump.

