

Humidity Indicators

A humidity indicator is a card on which a moisture-sensitive chemical is impregnated such that it will change color when the indicated relative humidity is exceeded.

